


E-shop: <http://eshop.prodance.cz/tr40/d-91680/>




Overlay Compare: dev= +1.6/-1.1, std= 0.72, avg= 0.75

AUDIX TR40A N.509194-129 / MBC-550 Nr.1059 ....

9-16-90 3:33 PM


MLSSA: Frequency Domain



Overlay Compare: dev= +2.1/-1.9, std= 0.91, avg= 0.9

AUDIX TR40A N.509194-129 / MBC-550 Nr.1059 ....

E-shop: <http://eshop.prodance.cz/tr40/d-91680/>




Overlay Compare: dev= +4.3/-3.6, std= 2.5, avg= 5

AUDIX TR-40 507256-9 ---- / MBC-550 Nr.1059 ....

2-1-88 1:39 AM


MLSSA: Frequency Domain



Overlay Compare: dev= +4.1/-3.8, std= 2.4, avg= 5

AUDIX TR-40 507256-9 ---- / MBC-550 Nr.1059 ....

E-shop: <http://eshop.prodance.cz/tr40/d-91680/>




Overlay Compare: dev= +4/-3.7, std= 2.3, avg= 7.1

AUDIX TR-40 507256-3 ---- / MBC-550 Nr.1059 ....

2-1-88 3:04 AM


MLSSA: Frequency Domain



Overlay Compare: dev= +3.6/-3.8, std= 2.2, avg= 7.2

AUDIX TR-40 507256-3 ---- / MBC-550 Nr.1059 ....

E-shop: <http://eshop.prodance.cz/tr40/d-91680/>




Overlay Compare: dev= +5.1/-4.2, std= 2.5, avg= -0.32

AUDIX TR-40 N.500225-76

4-24-09 1:45 AM

MLSSA: Frequency Domain



Overlay Compare: dev= +5/-3.2, std= 2.4, avg= -0.31

AUDIX TR-40 N.500225-76